

Welcome NYCHA Staff

- Registration & sign-in/out
- Training materials
- Training Agenda
- Training Goals
 - Understand importance of controlling mold & moisture
 - Be able to use the tools, practices & procedures
 - Be ready to get this done!






Welcome NYCHA Staff

- This training is presented by EEA under contract to NYCHA
- EEA is an accredited asbestos, lead & mold training provider
- We look forward to working with you to provide this very important training
- It's critical to public housing in NYC
- NYCHA succeeds when YOU succeed!
- General Manager's Intro



3

Public (Housing) Enemy #1





Why Are We Here Today?

- Because exposure to excessive moisture and mold is considered a major asthma trigger - IOM 2004, WHO 2009, and NYC DOHMH 2008
- Because the mold problems in NYCHA apartments keep coming back: 1) mold growth conditions are being painted over and paint is mold food; 2) the Root-Cause of the moisture conditions has not been identified and corrected.







5

Mold and the Asthma Epidemic in NYCHA Housing

- >400,000 low-income residents
- · Childhood asthma at epidemic levels (21.8%)
- In 2013, with help from LSAFHS and NRDC, NYCHA residents with asthma file class action lawsuit against NYCHA (Baez case). Residents prevail. Consent decree requires NYCHA to promptly and effectively identify and remediate mold and correct underlying moisture root causes.
- NYCHA violates consent decree court appoints Special Master



Health Inequity – Asthma in Low-Income Housing

Prevalence, Health Inequity, and Opportunity

Over 24 million Americans have current asthma (7.8% of US population)¹, CT 9.3%² Over 6 million American children have asthma $(8.4\% \text{ of US population})^1$, CT $10.5\%^2$ Wide health disparities in childhood asthma by housing type in NYC3



NYC Public Housing 22% asthma prevalence



Typical NYC Apartment 12% asthma prevalence



Private NYC Housing 7% asthma prevalence

¹ Center for Disease Control and Prevention. https://www.cdc.gov/asthma/mostrecentdata.html


² State of Connecticut Department of Public Health. A Collaborative Approach for Addressing Asthma in Connecticut, 2009-201 ENVIRONMENTAL

³ Northridge, Jennifer et al. "The Role of Housing Type and Housing Quality in Urban Children with Asthma." Journal of Working to make our communities hes

Urban Health: Bulletin of the New York Academy of Medicine 87.2 (2010): 211-224. PMC. Web. July 2016.

7

Asthma Prevalence Data



Northridge, et al. The role of housing type and housing quality in urban children with asthream to work associates. Journal of Urban Health, 2010; vol 87, no. 2.

NYCHA Facilities

- 2,413 buildings in 325 developments over five boroughs; 769 facilities; 177,666 apartments; 404,000 residents
- 70 percent of NYCHA buildings built before 1969.
- List of NYCHA Properties
- Building materials that can be affected by mold & moisture include:
 - Plaster
 - Drywall
 - Wood Studs/Framing
 - Cabinets



9

NYCHA Sustainability Agenda

- NYCHA is committing to systemically eliminating the root causes of mold by fixing leaks in roofs, facades, pipes and modernizing ventilation systems by 2025
- Next Generation NYCHA Sustainability Agenda



Where Does Mold Grow in NYCHA?

- The paint on plaster, concrete, and sheetrock walls/ceilings
- The paper covering of sheetrock walls/ceilings (front/back and top/bottom sides)
- · The covering of pipe-wrap insulation in wall cavities
- · Bathroom tile grout and caulking
- Kitchen and bathroom cabinetry
- · Wood framing materials in wall cavities



11

Preventing Mold In NYCHA



- Mold growth is always associated with excessive moisture problems.
- How do we prevent or control excessive moisture and what are the Root-Causes of excessive moisture?



Mold Root Causes

The fundamental reason(s) for the occurrence of mold, water damage or moisture.

- Identify and select the most correct root cause(s) to ensure the condition does not reoccur – up to four (4) can be selected.
- Root cause(s) might often be not visible at first and require a comprehensive investigation to identify.





13

Mold Root Causes

Twenty-nine (29) Root Causes are organized by <u>five (5) general</u> categories how the problem was caused.

- Sealant Related Issues Issues that can be resolved by removing and replacing old caulking. *Example*: Caulking around a bathtub.
- II. Leak Issues Issues caused by a leak other than an sealant issue. Example: Crack in exterior (façade) is causing a water enter the unit.
- III. Resident-Caused Issues that can be prevented due to adjustments to resident education and behavior. Example: Resident is not opening a window after a shower.
- IV. Ventilation Issues that are a result of inoperable roof fans and/or lateral duct issues. Example: A clog in the lateral duct is preventing air from flowing into the apartment.
- V. Other Issue(s) are being caused due to reasons outside of the four categories previously listed. Example: Condensation (sweating on the pipes) due to the damaged or missing insulation.



Root Cause Maintenance Work

- Toilet pulls
- Caulking
- Insulation/re-insulation
- Exhaust grill/duct/backflow damper cleaning
- · Fan belt replacement
- Plumbing repairs,



15

Water Infiltration

- Major cause of mold growth
- Present in app. 75% of all properties
- Moisture is the leading cause of building problems costing more than \$9 billion dollars annually in the US.



How Long Has Mold Been A Problem?

From Leviticus Chapter 14, verses 33-57

On the seventh day the priest shall return to inspect the house. If the mold has spread on the walls. He is to order that the contaminated stones be torn out and thrown into an unclean place outside the town. He must have all the inside walls of the house scraped and the material that is scrapped off dumped into an unclean place outside the town. Then they are to take other stones to replace these and take new clay and plaster the house.

If the mold reappears in the house after the stones have been torn out and the house scrapped and plastered the priest is to go and examine it and if the mold has spread in the house, it is a destructive mold: the house is unclean. It must be torn down - its stones, timbers and all the plaster - and taken out of the town to an unclean place.

Anyone who goes into the house while it is closed up will be unclean till evening.



Anyone who sleeps or eats in the house must wash his clothes...

17

How Mold Grows

- · Finds suitable conditions
 - Water
 - Food
 - Temp (hot or cold)
- Grows
- Spreads



Localized Mold Contamination





19

Major Mold Infestation





Efflorescence



- Efflorescence is the residue that's left behind when water seeps through concrete, stone, or brick.
- Salt deposits leave a white residue that resembles mold.
- Won't grow or spread, and isn't a fungus.

ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities healt.

NYCHA Mold Inspector

21

Exposures To Residential Dampness And Mold

Associated with increased risks of;

- Respiratory symptoms
- Asthma
- · Hypersensitivity pneumonitis
- Rhinosinusitis
- Bronchitis
- · Respiratory infections.



Preventing Mold Growth

Simple Steps

- keep exterior moisture out of the building
- control moisture from internal sources



23

Preventing Mold Growth

- It's important to establish a cooperative partnership between NYCHA staff and residents so that conditions that require attention are identified and dealt with promptly.
- NYCHA staff and residents should take action to detect and correct leaks, condensation problems, and floods as soon as they are discovered.
- The potential for building structural damage, mold growth, and increased adverse health effects can and should be reduced by limiting the buildup of indoor moisture

ENVIRONMENTAL EDUCATION ASSOCIATES

UPDATED - Top Ten Things NYCHA Staff Should Know About Mold & Moisture

- Potential health effects and symptoms associated with exposures to mold and excessive moisture include allergic reactions, asthma, and other respiratory complaints.
- Mold can be found almost anywhere; it can grow on virtually any substance if moisture is present. For example, there are molds that can grow on sheetrock, painted plaster and concrete, wood, paper, carpet, foods, and even dusty inorganic building materials
- 3. There is no practical way to eliminate all mold and mold spores in the indoor environment; the way to control indoor mold growth is to control moisture.
- 4. If mold is a problem in an apartment or building, we must clean up the mold and eliminate sources of moisture.
- 5. Fix the source of the water problem or leak to prevent mold growth, including repairing leaky roofs.

ENVIRONMENTAL
EDUCATION ASSOCIATES
Working to make our communities health

25

Top Ten Things NYCHA Staff Should Know About Mold & Moisture

- 6. Reduce indoor humidity (to 30-60%) to decrease mold growth by: venting bathrooms and kitchens; using air conditioners and de-humidifiers; and increasing ventilation. Staff shall ensure that mechanical ventilation is functioning (clear lateral ductwork and operable roof fans). Further, staff can use a hygrometer to check the relative humidity in a resident's apartment
- 7. Clean and dry any damp or wet building materials and furnishings within 24-48 hours to prevent mold growth.
- 8. Clean minor levels off off hard surfaces with water and detergent, and dry completely. Absorbent materials, such as sheetrock, that are moldy will need to be replaced.

ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities health

Top Ten Things NYCHA Staff Should Know About Mold & Moisture

- 9. Prevent condensation: reduce the potential for condensation on cold surfaces by assuring that cold water pipes in wall cavities are properly insulated.
- 10. If needed as a result of asthma, individuals with mold and/or excessive moisture in their apartments are entitled to reasonable accommodations from NYCHA.




27

NYCHA MOLD TRAINING EEA ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities healthy Health Effects

Why Is Mold A Problem Today?

- Recent discoveries linking the presence of mold with health problems
- Improved understanding of healthy housing









EEA

ENVIRONMENTAL
EDUCATION ASSOCIATES
Working to make our communities health

31



Mold Exposure

- Inhalation most common
 - Respiratory disease
 - Allergic reaction
 - CNS dysfunction
- Dermal irritation/infection
- Ingestion Infection



33

Mold Exposure Symptoms

- sneezing
- runny nose
- coughing
- wheezing
- watery eyes
- redness of the eyes
- itchy eyes
- skin irritation, or rash



Health Effects

• "Breathing Mold Can Cause Health Issues" - IAQ TV



35

Potential Health Effects

- Allergic reactions/disease
- Irritant effects
- Infections
- Toxic effects





Allergic Responses

- Reactions can be immediate or delayed.
- Reactions can result from inhaling or touching mold or mold spores.
- Mold spores and fragments, whether dead or alive, can produce allergic reaction in sensitive individuals.
- Repeated or single exposure may cause previously nonsensitive individuals to become sensitive.
- · Repeated exposure has the potential to increase sensitivity.



37

Allergic Responses

Hay fever-type symptoms

- Sneezing
- Runny nose
- Red eyes
- Skin rash (dermatitis)



Allergic Responses

Asthma

- Molds can trigger asthma attacks in persons allergic (sensitized) to molds.
- Asthma is a major problem in New York City. In some lowincome parts of New York City, as many as one in four children have asthma





39

Asthma Prevalence Data

United States

20 million - 1 in 15 or 6.7% ¹

New York City

• 813.000 - 1 in 7.5 or 13.5% ²

East Harlem

• 20,000 - 1 in 5 or 19.6% ²



^{2.} NYC DOHMH Community Health Survey



Allergic Responses

Hypersensitivity pneumonitis (HP)

- Rare, but serious, immune-related condition resembling bacterial pneumonia
- May develop after either acute or chronic exposure (via inhalation) to molds
- Usually related to occupational exposure
- Can also be caused by bacteria



41


Uncommon Allergic Syndromes

- Allergic bronchopulmonary aspergillosis
- · Allergic fungal sinusitis



Irritant Effects

- Irritation of:
 - Eyes
 - Skin
 - Nose
 - Throat
 - Lungs





43

Irritant Effects

Mold exposure can irritate the eyes, skin, nose, throat, and lungs of both mold-allergic and non-allergic people.





Microbial Volatile Organic Compounds (mVOCs)¹

- · Produced by molds and released into air
- Often have strong and/or unpleasant odors
- Exposure linked to symptoms such as headaches, nasal irritation, dizziness, fatigue, nausea
- · Health effects research in early stages



45

Toxic Reactions

- Some molds can produce toxic substances called mycotoxins.
- Some mycotoxins are on the surface of mold spores; others are within the spore.
- Over 200 mycotoxins have been identified from common molds.



Mycotoxins


- Medical evidence of whether mold growing in homes or offices causes health effects in occupants due to mold toxins is lacking.
- * Research is needed.



47

Degrees of Exposure

- "The dose makes the poison" (in <u>Latin</u>: sola dosis facit venenum) – Paracelsus (1538 AD)
- a substance can produce the harmful effect associated with its toxic properties only if it reaches a susceptible biological system within the body in a high enough concentration
- Occupants or remediation workers disturbing large areas of mold growth face greater exposure potential, and thus, greater potential for adverse health effects.





Common-Sense Approach

- Small amounts of mold growth in homes and buildings are common occurrences, that for the majority of people present minimal health risks.
 - The solution is to fix the moisture problem and clean up the mold quickly.
- Large areas of mold growth present a more likely risk of exposure and adverse health effects for some people.
 - Large areas of mold growth indicate more extensive water damage/moisture intrusion in the building.
 - Additional and more extensive measures should be used during remediation to protect both workers and occupants of the building.



49

Unknowns

- There are insufficient data to determine if molds cause other adverse health effects, such as pulmonary hemorrhage, memory loss, or lethargy.
- We do not know if the occurrence of mold-related illnesses is increasing.
- Other than surveillance for hospital-acquired infections, there
 is no system to track the public's exposure to and the possible
 health effects of mold.



Health Issues for Workers

- Mold assessment and remediation employees with persistent health problems that appear related to mold should see a physician.
- Referrals to physicians trained in occupational, environmental or allergy medicine may be needed.



51

Health Issues for Workers

- During mold remediation projects, workers could be exposed to other substances or hazardous materials that could cause adverse health effects:
 - Asbestos
 - Lead-based paint
 - High levels of particulates
 - Bacteria (associated with water-damaged materials, floods, sewage backups)
 - Cleaning products/biocides used as part of the projects



Golden Rule for Mold Exposure Safety

Minimizing mold-related exposures will reduce the possibility of health impacts on occupants and workers.

- As the potential for exposure increases, the need for protective measures increases.
- Workers can reduce exposure potential by proper use of personal protective equipment (PPE).
 - Respirators (Minimum N-95)
 - Gloves
 - · Protective clothing
 - Goggles



53

Dealing with the Public

- Do not give medical advice to residents.
- Tell them to consult a health care provider regarding any health effects they might be experiencing.



NYCHA MOLD TRAINING



55

Public Awareness

DAILY®NEWS

NYC Housing Authority to come under judicial oversight over mold in apartments



A child in a NYCHA apartment with mold on the wall. The New York City Housing Authority will come under federal judicial oversight over mold in apartments, enabling residents to go directly to a federal judge if the a

- Receiving Attention
 - Media
 - Medical
 - Legal
- Baez Lawsuit











Ohio chief justice speaks at seminar about fairness

Ohio Supreme Court Chief Justice Thomas Moyer acknowledges racial unfairness in Ohio's legal system during speech in Cuyahoga Falls.

Election panel allows secret group's TV ad

Ohio Elections Commission panel dismisses complaint against a TV ad opposing Ohio Supreme Court justice. The Beacon Joi

October 20,

www.ohio.com/bj

Mold cleanup starts at apartments

Akron housing authority spending \$800,000 to scrub Joy Park complex

By Bob Downing

The Akron Metropolitan Housing Authority will spend an Joy Park apartment buildings in Tony O'Leary.

Cleanup of the Copley Road estimated \$800,000 to check for apartments by Cardinal Environand deal with a potentially dan-gerous greenish-black mold in said AMHA Executive Director ment in the same building.

southeast Akron.

The cleanup involves removing agency also is in the process of removing the same slimy mold - called stachybotrys

The agency also is in the process of removing the same slimy mold - called stachybotrys

The deanup involves removing the two temperatures and the two temperatures and the two temperatures and the two temperatures are processed in the two te

- from two of its empty apart-ments on Copley Road in south-one Copley Road apartment by AMHA staffers after its tenants had moved out. It also was found in an area damaged by a leaky

No complaints were filed by

The mold was discovered in ed to begin Nov. 13, will include checking 23 empty buildings for the mold behind the walls and removing it, O'Leary said. In addition, new waterproof wallboard will be installed in the at Joy Park: the 23 where the said. buildings to reduce the likeli-hood that the mold will come

"It's not yet resolved," he said cious," O'Leary said.

of the mold problem. "It's something we're still working on very of any mold problems or com-

AMHA officials met yesterday with contractors, and bids for the Joy Park mold abatement work will be opened Oct. 31, O'Leary said.

The housing authority owns 41 buildings with 200 apartments mold work will be done, two
empty buildings to be razed and
lo occupied buildings, said construction manager Tom Gilbert.


He said the AMHA h
knowledge that any Joy Pare LA
environmental transfer and the said the AMHA h
through through the said the AMHA h
through the said the said the AMHA h
through the said the said the AMHA h
through the said the sa

cupied and recently reno buildings.


AMHA intends to che mold in the occupied buil after the agency gets a lidea of the scope of the pri in the empty buildings, O

Please see Mo

ENVIRONMENTAL EDUCATION ASSOCIATES









SACRAMENTO BUSINESS JOURNAL 5

61



OENNIS Macox / SACRAMENTO BUSINESS /OURNAL Tom Anderson, with son Alan, said Alistate offered \$17,300 to do \$30,000 in nome repairs

Mold verdict: \$18 million

KELLY JOHNSON / STAFF WRITER

RELLY JOURNEN / STAFT WHITE

A federal court jury in Sacramento on Tuesday awarded a 98-year-old Placerville man \$181 million in punitive damages in his bad-faith instance Co.

"Allstate could have repaired my house for a little over \$30,000 to start with," Tom Anderson said after the decision.

"Allstate, the nation's second-largest home and car insurer, plans it appeal.

Anderson's house was damaged more than 3½-year-ago when a water pipe burst and mold took hold throughout the modest structure. He rejected Allstate's offer of \$17,000 to repair the house and said Allstate in July 1598.

Auterson won't collect any money while the case is on appeal. "Usually it's a two-to-three-year process," said Ron Haven of the plantiff's law firm, Shepard & Haven, in Sacramento, Anderson's lead attorney was Stan Parrish.

son said, he had killed down the mold, but

son said, he had killed down the mold, but didn't eliminate it. Now the house must be torn back down to the frame.

At Iral, an Allstate expert disagreed.

Torn Anderson, who has been living with his son, misses his own home, yard and neighbors.


A year ago Alan Anderson figured that Allstate was waiting for his father to die because the bad-faith hiswait would have died with him. Now, if Torn Anderson were to die before the appeal is decided, the conomic and punitive damages would remain, while the non-extomoric damages would be lost. Haven said.


"It is a hig victory," Alan Anderson said, "for the little guy."



CB A Richard Ellis

"Bringing CB Richard Ellis in to help plan and coordinate our corporate can ject was SSOCIATES





NYCHA Mold Busters

Better Tools

 Staff will use new tools to find and fix the source of the problem, including moisture meters and new mold-fighting paint.

Enhanced Training

 Staff will receive additional hands-on training to become successful Mold Busters.

More Accountability

– A new inspection and recording process requires photos of the affected areas and guides the staff through the process of finding the cause of the mold or moisture problem. NYCHA will also inspect apartments after the work is completed to ensure that the staff has properly fixed the condition, and there is no mold.

> ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities health

65

NYCHA Tech Service Mold Unit

- Coordinate classroom training for over 2,500 operations staff, including property management and front line staff.
- Conduct field training to ensure adherence to Mold Standard Procedure and process.
- Facilitate distribution of all Mold Busters tools.
- · Communicate with all NYCHA residents.
- Coordinate and prioritize mold work order scheduling to streamline repairs.

ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities healthy

NYCHA Policies

- It is the policy of NYCHA to establish a cooperative partnership between staff and residents to quickly identify mold and its root causes.
- NYCHA will promptly remove mold from NYCHA locations and identify and correct the root cause of the mold growth; i.e., the moisture source and/or inadequate ventilation.



67

NYCHA Purpose

 Standard Procedures establish responsive measures to mold and its root causes in NYCHA public housing locations, and creates protocols to protect the health of residents and staff when remediating mold and identifying and correcting its root causes.



Standard Procedures

- Inspections

All inspection work must conform to the protocols in the following documents:

- GM 040:14:1, Mold/Mildew Control in NYCHA Residential Buildings
- NextGeneration NYCHA Informer Work Management (iWM) handheld application



69

Standard Procedures

- Remediation

All remediation & related maintenance work must conform to the protocols in the following documents:

- GM 040:14:1, Mold/Mildew Control in NYCHA Residential Buildings, including Appendix A – Remediation Methods
- GM-040:18:2 Revised, Maintenance Tasks Dust Control and Clean Up in Apartments, which establishes Work Area Preparation/Performance Levels
- · Interim Guidance on Wall Breaks
- · Interim Guidance on Pipe Insulation



Training Requirements

- Inspector (32 hrs) Training on inspection tools and methods as well as conducting and documenting inspections
 - Directors, Regional Asset Managers, Housing Managers, Resident Building Superintendents, and Assistant Resident Building Superintendents
- Building Sciences (16 hrs) Training on identifying the root causes of mold and on the methods to correct the root causes to prevent the reoccurrence of mold.
 - Directors, Regional Asset Managers, Housing Managers, Resident Building Superintendents, Assistant Resident Building Superintendents, and Maintenance Workers
- Remediation Methods (8 hrs) -Training on how to safely and effectively remediate mold and its root causes.
 - Skilled Trades, Painters, and Caretaker (P)

EEA

ENVIRONMENTAL
EDUCATION ASSOCIATES
Working to make our communities health

71

Performance Metrics

- Average number of days to complete repairs and close mold work orders.
- Average number of days to complete initial inspections.
- Percent of mold work orders for reoccurring mold.



Non-compliance

- If unsatisfactory work is identified during a quality assurance inspection in Section VIII.H, or at any other time, supervisory staff must take one or more of the following actions:
 - Identify areas for follow up training for the employee and ensure training is scheduled and provided.
 - Reinforce with the employee(s) the job expectations, accountabilities, and the progressive discipline process.
- Failure to comply with the requirements of this Standard Procedure may result in disciplinary actions.



73

Other Agency Guidelines

New York City Department of Health and Mental Hygiene "Guidelines on Assessment and Remediation of Fungi in Indoor Environments" – 2008

- Environmental Assessment
 - Visual Inspection
 - Environmental Sampling
- Communication with Building Occupants



Other Agency Guidelines

New York City Department of Health and Mental Hygiene "Guidelines on Assessment and Remediation of Fungi in Indoor Environments" – 2008

- Remediation
 - Moisture Control and Building Repair
 - Worker Training
 - Cleaning Methods
 - Quality Assurance Indicators
 - Restoring Treated Spaces



75

Other Agency Guidelines

New York City Department of Health and Mental Hygiene "Guidelines on Assessment and Remediation of Fungi in Indoor Environments" – 2008

- Remediation Protocol
 - Small Isolated Areas (less than 10 square feet) e.g. ceiling tiles, small areas on walls
 - Medium-Sized Isolated Areas (10 100 square feet)
 - Large Areas (greater than 100 square feet in a contiguous area) e.g. on separate walls in a single room



Other Agency Guidelines

New York City Department of Health and Mental Hygiene "Guidelines on Assessment and Remediation of Fungi in Indoor Environments" – 2008

- Remediation of HVAC Systems
 - Small Isolated Area of Mold Growth in the HVAC System (<10 square feet) e.g. box filter, small area on insulation
 - Large Area of Mold Growth in the HVAC System (>10 square feet)



77

Other Agency Guidelines

EPA Mold Remediation in Schools and Commercial Buildings - 2008

- Mold Remediation Key Steps
- Plan the Remediation Before Starting Work
- Remediation Planning
- HVAC System



Other Agency Guidelines

EPA Mold Remediation in Schools and Commercial Buildings – 2008

- Remediation
 - Table 1: Water Damage Cleanup and Mold Prevention
 - Table 2: Mold Remediation Guidelines
 - Cleanup Methods
 - Personal Protective Equipment (PPE)
 - Containment
 - Equipment



79

Other Agency Guidelines

OSHA "Brief Guide to Mold in the Workplace" - 2013

- · Skin and Eye Protection -
- · Respiratory Protection
- · Protective Clothing
- · Remediation methods per EPA/NYC
- Sampling Not Recommended for visible mold
- Equipment for Assessment & Remediation



Trade Organization Protocols

IICRC S520 - a procedural standard and reference guide for the remediation of mold damaged structures and contents and is based on reliable remediation and restoration principles, research and practical experience, and attempts to combine essential academic principles with practical elements of water damage restoration for technicians facing "real-life" mold remediation challenges.

ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities health

81

NYS Article 32

- Signed by Governor January, 2015
- Establishes certification and licensing program with fees
- Provides for accreditation of training providers
- Establishes standards for assessment & remediation
- Defines practices & procedures
- Serves as the basis for this training



NYS Article 32

- Enforced by NYS Dept of Labor Division of Safety & Health
- Assigns Roles & Responsibilities
 - Mold Assessors
 - Mold Remediation Contractors
 - Mold Abatement Supervisors
 - Mold Abatement Workers



83

NYS Article 32

Establishes Standards for:

- Mold Remediation Plans by Assessors
- Mold Remediation Work Plans by Contractors
- Post–remediation Assessment by Assessors



NYS Article 32

EXEMPTIONS


- A residential property owner who performs mold inspection, assessment, remediation, or abatement on his or her own property;
- A non-residential property owner, or the employee of such owner, who performs
 mold assessment, remediation, or abatement on an apartment building owned by
 that person where the property has four or less dwelling units;
- An owner or a managing agent or a full-time employee of an owner or managing agent who performs mold assessment, remediation, or abatement on commercial property or a residential apartment building of more than four dwelling units owned by the owner. This exemption will not apply if the managing agent or employee engages in the business of performing mold assessment, remediation, or abatement for the public; and
- A federal, state or local governmental unit or public authority and employees thereof that perform mold assessment, remediation, or abatement on any property owned, managed or remediated by such governmental unit or authority.

ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities healt

85

NYCHA MOLD TRAINING EEA ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities healthy Practices

86





87

Mold Evaluation & Testing Practices

- The goals for a Mold Assessment is to find the mold and determine its extent so that it can be removed in a safe manner.
- However the differences as to how to properly perform mold assessment can be substantial.
- Some, such as EPA, focus on finding the moisture and you find the mold.
- Others, such as IICRC, focus mostly on sampling to develop remediation procedures.
- We look at these differences and discuss approaches to mold assessments that are most often used by mold remediation professionals.
- We also look at NYSDOL requirements for the compiling of information for use in a Mold Remediation Plan

ENVIRONMENTAL EDUCATION ASSOCIATES

Mold Evaluation & Testing Practices

Should:

- Focus on **presence** and **location** of mold.
- Determine the **extent** (of hidden mold),and **origin** (cause) of mold.





89

Mold Evaluation & Testing Practices

Sometimes Includes:

- Pictures of the problems / problem areas.
- · Determination of Hidden Mold in Walls.





90

Step 1 - Walk-Through Inspection

- · Step A involves:
 - Visual, non-destructive inspection
 - A careful walk-through inspection will include close observation of accessible interior surfaces using common inspection tools, notes and photographs.





91

Step 1 - Walk-Through Inspection

 Investigate any noticeable odors or visible evidence of fungal growth, and any blisters, stains, corrosion, deterioration, or discoloration that might indicate water intrusion or condensation problems





Step 1 - Walk-through Inspection: Where to Look

All surfaces should be closely inspected, especially:

- · seams and crevices along the base of walls
- · edges of carpets
- · seams of wall fabrics
- · the base of all window and door jambs
- · tops of walls
- · joints in ceiling materials
- airstream surfaces of accessible air conditioning or humidification equipment





93

Step 1 - Walk-through Inspection: Where to Look

- Organic substrates wetted by water are the most common amplification sites, but even elevated relative humidity or dust on hard surfaces might support growth.
- The inspector should first look for any evidence of liquid water from leaks or condensation.





Step 2 - Invasive Inspection and Investigation

- Locations for invasive inspection are chosen where mold colonization is most likely
- Based on visual evaluation of exposed surfaces, experience with similar construction.
- Review of building plans.
 - Other locations should be selected to view representative conditions where mold is not expected, to confirm its absence or identify the unexpected.





95

Step 2 - Invasive Inspection and Investigation : Ventilation

Inspection should include ventilation systems where present.

 Dirty ventilation grills & ducts might be the source of contamination, or the means of its distribution between spaces, or might indirectly contribute to the concentration of indoor air contaminants by providing inadequate ventilation.





Procedure for Inspection of Wall Cavities

- The goal is to inspect every wall cavity in the area under investigation, identify the location and extent of mold growth in each wall cavity, and delineate areas requiring remediation.
- Destructive investigation will likely result in release of contamination, so containment, safe work practices and personal protective equipment is necessary



97

Procedure for Inspection of Wall Cavities

 Where visible contamination extends up into the wall cavity above, and where leaks from overhead roofs, decks, windows, or pipes are suspected, smaller openings should be made high on walls or ceilings, so that the leak source and extent of contamination can be identified.





Procedure for Inspection of Wall Cavities

- Mold growth is likely to be present on the paper covering on the back side of sheetrock in areas that
 - measure wet.
 - display water damage
 - have a reported history of water damage

The cellulose content of this paper covering provides ideal nutrient for the development of *Stachybotrys* type mold growth



99

Mold Root Causes

Twenty-nine (29) Root Causes are organized by <u>five (5) general</u> categories how the problem was caused.

- Sealant Related Issues Issues that can be resolved by removing and replacing old caulking.
 Example: Caulking around a bathtub.
- II. Leak Issues Issues caused by a leak other than an sealant issue. Example: Crack in exterior (façade) is causing a water enter the unit.
- III. Resident-Caused Issues that can be prevented due to adjustments to resident education and behavior. Example: Resident is not opening a window after a shower.
- IV. Ventilation Issues that are a result of inoperable roof fans and/or lateral duct issues. Example: A clog in the lateral duct is preventing air from flowing into the apartment.
- V. Other Issue(s) are being caused due to reasons outside of the four categories previously listed. Example: Condensation (sweating on the pipes) due to the damaged or missing insulation.



I. Mold Root Causes – Sealant Related Issues

Issues that can be resolved by removing and replacing old caulking or grouting.

Example: Caulking around a bathtub.

Caulking - Is a material used to seal joints or seams against leakage in various structures and piping. <u>Maintenance and Plaster.</u>

Grouting – A dense fluid which is used to fill gaps or used as reinforcement in existing structures. Grout is generally a mixture of water, cement, and sand. Grout is thin so it flows readily into gaps. Bricklayer.





101

I. Mold Root Causes – Sealant Related Issues

- Caulking DML (Maintenance)
 The maintenance worker will follow-up on this work order and do the caulking.
- Grouting DML (Bricklayer)
 A bricklayer, craft, will follow-up on this work order and do the grouting.
- Grouting DML (Plasterer)
 A plasterer, craft, will follow-up on this work order and do the grouting.
- Grouting/ Caulking DML (Plasterer)
 A plasterer, craft, will follow-up on this work order and do the grouting / caulking work.
- Grouting/ Caulking DML (Bricklayer)
 A bricklayer, craft, will follow-up on this work order and do the grouting/ caulking.



II. Mold Root Causes - Leak Issues

Issues caused by a leak other than a sealant issue.

- Leak Around Window
 Lack of sealant around the window that causes water to penetrate.
- Leak Through Façade
 A crack or damaged/missing mortar affecting the exterior wall.
- Leak From Above/Beside Investigate
 There is an active leak from a unit above or beside the unit with a mold condition.
- Leak From Above * Previously Identified
 There was a leak that was abated but mold/ water damage remain present.
- Plumbing Leak In Unit
 A pipe leaking within the wall cavity requiring a wall break.

CIATES
nunities health

103

Plumbing Leaks/Flooding







Perimeter Wall Condensation







105

II. Mold Root Causes – Leak Issues (continued)

Leak From Above - Previously Identified

Previously Identified should be selected when the root cause or remediation work for the mold, water damage, or wet condition had been identified or abated by Property Maintenance staff or Skilled Trades on a prior work order.

A note and pictures are required for this root cause.



II. Mold Root Causes – Leak Issues (continued)

- Roof Leak Non Capital Roof replacement or repair is required.
- Sink Supply Line Leak
 Caused by a leak(s) in the supply line.
- Sink Waste Line Leak
 Caused by a leak(s) in the waste line.
- Toilet Leak
 Active leak coming from the toilet.





107


II. Mold Root Causes – Leak Issues (continued)

Leak From Above - Previously Identified *

- 1) Pre-inspection to look-up leak history for the specific unit.
- 2) Does not cancel or duplicate previous generated tickets.
- 3) Escalates the matter if root cause is being caused by something else if it keeps reoccurring.



Façade Leaks





109

Roof Leaks









110

Toilet Condensation - From Above











111

III. Mold Root Causes – Resident-Caused

Issues that can be prevented due to adjustments to resident education and behavior.

Examples:

- Not opening the window for ventilation during, or after, a shower.
- · Covering the roof fan vent.
- Improper installation of a dishwasher or washing machine.
- Improper installation of a clothing dryer in the apartment.





III. Mold Root Causes – Resident-Caused

- Resident-Caused (Code 1)
 Resident doesn't open the window or door after taking a shower
- Resident-Caused (Code 2)
 Dishwasher was installed improperly.
- Resident-Caused(Code 3)
 Washing machine was installed improperly.
- Resident-Caused (Code 4)
 Vent is blocked or covered.



- Resident-Caused (Code 5)
 Clothing dryer was installed improperly.
- Resident-Caused (Code 6) *
 Other the option was not listed.



113

III. Mold Root Causes – Resident-Caused. (continued)

Resident-Caused by Other Actions (Code 6) *

Mold Busters Education will be needed for the resident(s) for future prevention of mold. A mandatory inspection will be needed to find the exact reason(s).

A note and pictures are required for this root cause.



III. Mold Root Causes – Resident-Caused. (continued)

Resident-Caused by Other Actions (Code 6) *

Examples:

- Excessive boiling of pots.
- Unbalanced hot/cold temperatures in the unit and/or units above, below, or adjunct.

A picture and an explanation is needed for the reader to understand the reasoning for selecting this root cause.



115

V. Mold Root Causes - Other

- Toilet Bowl/ Tank Needs Barrier
 - Toilet tank is in direct contact with the surface of the wall, allowing condensation to transfer across surfaces.
- Tub Surround DML
 - Water is penetrating through missing or damaged areas of the tub surround.
- Bathtub Shower Issues
 - Bathtub is missing, faucet is leaking, faucet is running, and/or faucet is dripping.
- Pipe Insulation DML
 - Damaged or missing pipe insulation resulting in condensation (or sweating) on pipe surfaces. A wall-break is required to diagnose this problem.
- Other * This option should be selected if the root cause is not listed or not
 evident through the standard assessment practices.



Condensation on Cold Water Pipes In Wall Cavities



Missing insulation on cold water riser



Damaged insulation on cold water riser



Missing insulation on cold water supply t



117

Shower Vapor Condensation







118

Cold Weather Condensation



- Can occur when warm moist interior air contacts cooler surfaces such as windows.
- Condensation forms
 when the surface
 temperature is below the
 dew point temperature
 for the interior air



119

Warm Weather Condensation



- Can occur when warm moist interior air contacts cooler surfaces such as cold water pipes.
- Toilet tanks containing cold water often causes condensation
- Hot showers can cause condensation on "warm" surfaces



120

Toilet Condensation - In Apartment







121

Measurement Equipment

- On-site testing equipment that indicates if moisture or ventilation problems may be present
- Used to help identify root causes
- Provides immediate information
- Inspector must be able to operate and understand data



Inspection Equipment

- Moisture Meter
- Hygrometer
- Anemometer
- Boroscope









123

Field Measurements

- Moisture meter for moisture content in building materials
- Hygrometer measures humidity levels
- Anemometer provides air flow in CFM
- Boroscope allows view behind walls and other cavities



Moisture Meters

Protimeter Survey Master

Pin-probe Mode Measurements given as % moisture

Note: Pin-probe readings can provide additional information, but are not used during the root-cause assessment.





125

Hygrometer

- A hygrometer is used to measure moisture content in the atmosphere.
- Humidity measurement instruments usually rely on measurements of some other quantity such as temperature, pressure, mass or a mechanical or electrical change in a substance as moisture is absorbed.





Anemometers

- Used for measuring the speed of air
- Vane Anemometers use a remote fan (vane) that freely rotates in response to air flow





127

Hands-on **Demonstration**

Evaluation Equipment & Calibration

- Utilize boroscope to identift cavity contents
- Determine Relative Humidity (RH%) Testo
- Measure Ventilation Rate (CFM) Testo



Anemometers

- NYCHA uses Testo Vane instrument
- Must be set to Cubic Feet per Minute (CFM) - unit for Air Volume measurements.
- NEW Must be calibrated to 55% free air





129

Boroscope

- A boroscope is a hand-held tool that allows users to see potential mold problems inside walls, ceiling plenums, crawl spaces, and other tight areas.
- It consists of a video camera on the end of a flexible "snake."
- No major drilling or cutting of dry wall is required.





Precautions

- Investigating hidden mold problems may be difficult and will require caution when the investigation involves disturbing potential sites of mold growth.
- Safe work practices & personal protective equipment should be used if mold contamination is present that may be disturbed





131

Mold Busters App

- Mold Inspection Procedures
- Designed by & for NYCHA Housing
- Critical for recording results of inspection
- Used to determine remediation work orders
- Integrated into Maximo



MOLD/MILDEW WO Workflow - (Continued) Mold is Found ...Doing the Work (Part 1)...





December 2018

Handheld informer Work Management Training – Mold Inspection



133

MOLD/MILDEW WO Workflow - (Continued)

Mold is Found ... Doing the Work (Part 2)...





December 2018



Work Order Workflow

Doing the work...





December 2018

Handheld informer Work Management Training – Mold Inspection



135

Work Order Workflow

Ending the work...





December 2018



Samsung Galaxy S8 Device

Display: 5.8 inches

Cameras:

Rear 12MP w/Flash

Front 8MP

Storage: 64GB Device 4GB RAM

Software: Android 8.x

Talk Time: Up to 20 hours





December 2018


Handheld informer Work Management Training – Mold Inspection



137

View Work Order Details







December 2018



NYCHA Locations Explained

Examples of NYCHA Locations:

- Developments
- Buildings
- Stair Halls
- Floors
- Apartments

- Rooms (bedroom, bathroom, etc.)
- Heating Plumbing Line
- Grounds
- Elevators
- Community Centers

005.01.001.F02.02C.KIT01

Development #/ Building / Stair Hall / Floor / Apartment / Room 005. 01. 001. F02. 02C. KIT01




ecember 2018

Handheld informer Work Management Training – Mold Inspection



139

View Work Order Details








December 2018

Handheld informer Work Management Training – Mold Inspection



140

Inspection Status








December 2018


Handheld informer Work Management Training – Mold Inspection



141

Perform Inspection








December 2018



Evaluation of Mold Growth – (Continued)






December 2018

Handheld informer Work Management Training – Mold Inspection



143

Evaluation of Mold Growth – (Continued)








December 2018


Handheld informer Work Management Training – Mold Inspection



144

Evaluation of Mold Growth – (Continued)








December 2018

Handheld informer Work Management Training – Mold Inspection
Page 145



145

Evaluation of Mold Growth – (Continued)








December 201



Evaluation of Mold Growth – (Continued)







ecember 2018

Handheld informer Work Management Training – Mold Inspection



147

Evaluation of Water Damage

The second Mandatory
question on the Evaluation of
Conditions screen is: "is there
Water Damage?"

Tap NONE next to is there
Water Damage?






December 2018

Handheld informer Work Management Training – Mold Inspection



Evaluate Moisture Measurement Level








December 2018


Handheld informer Work Management Training – Mold Inspection



149

Perform General Evaluation Inspection









December 2018

Handheld informer Work Management Training – Mold Inspection



Perform General Evaluation Inspection – (Continued)








ecember 2018

Handheld informer Work Management Training – Mold Inspection



151

Perform General Evaluation Inspection - (Continued)








December 2018



Perform General Evaluation Inspection – (Continued)







December 2018

Handheld informer Work Management Training – Mold Inspection




153

Perform General Evaluation Inspection - (Continued)

If there was NO Exhaust Fan, the Supervisor shall answer "Is Window Operable?" question as YES or NO.

Tap on View Details below the Window Operable field to review information entered.

NOTE: If the Supervisor answers NO for Window Operable question, Maximo will autogenerate a Work Order to fix the window, upon submission of inspection results.







December 2018



Perform General Evaluation Inspection – (Continued)







December 2018

Handheld informer Work Management Training – Mold Inspection

Page 155



155

Probable Causes And Remediation

The third task in a series of tasks is

Task 3: Probable Causes and Remediation

1 Tap INSPECT






December 2018



Probable Causes And Remediation - (Continued)








December 2018

Handheld informer Work Management Training – Mold Inspection

ining – Mold Inspection

157

Probable Causes And Remediation - (Continued)








December 2018

Handheld informer Work Management Training – Mold Inspection



Probable Causes And Remediation – (Continued)





December 2018


Handheld informer Work Management Training – Mold Inspection
Page 159



159

Probable Causes And Remediation – (Continued)









December 201

Handheld informer Work Management Training – Mold Inspection



Probable Causes And Remediation – (Continued)








December 2018

Handheld informer Work Management Training – Mold Inspection



161

Probable Causes And Remediation – (Continued)








December 2018

Handheld informer Work Management Training – Mold Inspection



Probable Causes And Remediation - (Continued)





December 2018

Handheld informer Work Management Training – Mold Inspection
Page 163



163

Conclusion

- Responsible and effective problem evaluation will depend on the skill and experience of the inspector, but will also benefit from consistent use of standard protocols that can be adapted to individual project needs.
 Various steps of inspection and investigation may be required, depending on the complexity and extent of the problem.
- All inspection efforts require identification of the extent and location of mold growth and determination of root cause(s).







Remediation Overview

• Remediation Planning



167

Remediation Basics

- · Get rid of the water!
- Get rid of the food!
- Kill, then control!
- Don't forget the air!
- Vac! Wash! Vac!





Containment

- Containment
 - -plastic sheeting, duct tape
 - -exhaust fan with HEPA filter
 - -allow for decontamination, staging areas
- Control of Exposure
 - -vacate adjacent areas as appropriate



169

Containment





Remediation Basics

- · Restrict access to work area
- Construct containment & install engineering controls
- Remove contaminated and water damaged porous building materials
- Clean & decontaminate non-porous materials
- Clean & seal exposed surfaces
- Evaluate for completeness of work



171

Remediation Procedures

- 1. All remediation work must conform to the protocols in the following documents:
- SP 040:18:2 Revised, Maintenance Tasks Dust Control and Clean Up in Apartments, which establishes Work Area Preparation/Performance Levels
- Appendix A, Remediation Methods
- · Interim Guidance on Wall Breaks
- Interim Guidance on Pipe Insulation



Correcting Root Causes

Employees must ensure that all repairs to correct root causes:

- · Are completed to industry standards.
- Conform to the protocols in the following documents:
 - SP 040:18:02 Revised, Maintenance Tasks Dust Control and Clean Up in Apartments, which establishes Work Area Preparation/Performance Levels.
 - Interim Guidance on Wall Breaks
 - Interim Guidance on Pipe Insulation
 - Interim Guidance on Roof Fan Inspections
- Are documented with photographs



173

Remediation Procedures

- 2. All work must be documented with photographs, including at least one close-up photo of the condition(s) and at least one photo of the larger area.
- Employees must take and upload photos into Maximo using the handheld device of:
- The condition before work is performed.
- The condition after work is completed.
- Other photos as needed to demonstrate that work behind a surface was completed to standard, e.g. photos of insulated pipes, mold free areas.

ENVIRONMENTAL
EDUCATION ASSOCIATES
Working to make our communities health

Remediation Procedures – Note!

If cracked or crumbling tile is present, staff must:

- · cover the exposed area of floor with plastic
- · tape all edges securely with duct tape
- instruct the resident not to disturb the covered area
- contact the Technical Services Department's Asbestos Unit for further instructions.



175

Remediation Procedures – Note!

Any work that would disturb more than 2 square feet per room in a unit which could contain lead-based paint must use lead-safe work practices and RRP certified workers.



SP 040:18:2 – Performing Work

 For painted surfaces, if a component is to be removed from an underlying surface, score the perimeter/edge of the component with a utility knife to minimize the quantity of painted surface that is impacted.



177

SP 040:18:2 – Preforming Work

 Using the spray water bottle, spray the surfaces that will be disturbed to limit the creation and dispersal of dust. Periodically rewet the area while working



SP 040:18:2 – Performing Work

 If power tools are used that impact lead-based paint, only those equipped with a vacuum attachment connected to a HEPA vacuum are allowed to be used.



179

SP 040:18:2 – Performing Work

Observe safety precautions in contained work areas:

- Do not eat or drink in the work area.
- Keep polyethylene sheeting away from open flames, e.g. stoves and blowtorches.
- Exercise caution when spraying in the vicinity of electrical outlets.
- Prevent children and pets from entering the work area.



SP 040:18:2 – Performing Work

 Immediately repair torn sheeting using duct tape for minor tears. Total sheet replacement may be necessary for major tears.



181

SP 040:18:2 – Performing Work

The following work practices are prohibited:

- Open flame burning or torching of painted surfaces.
- Use of machines that remove paint or other surface coatings through high-speed operation, unless they have shrouds or containment systems and are equipped with a HEPA vacuum attachment.
- Operating a heat gun on painted surfaces above 1100 degrees Fahrenheit or charring the paint.
- Paint stripping using a volatile stripper in poorly ventilated space.
- Dry sanding or scraping, except within one (1) foot of electrical fixtures
 (e.g. switches, outlets, light fixtures, breaker boxes).



183

HEPA Filtration

• 99.97% efficient to 0.3 microns







HEPA Exhaust Containment







185

Cleaners & Disinfectants

- · Specialized chemicals for mold remediation
- · Anti-microbial cleaners used first
- Disinfectants used AFTER cleaning is complete
- NYCHA Products





Sodium Hypochlorite (Bleach)



Disadvantages

- Not compatible with all surfaces
- Safety issues
- Not a cleaner
- Inactivated by heavy organic soil
- Unstable



187

Follow Manufacturer's Directions

- Use the right dilution
- Use the right application
- · Change solution when recommended
- Avoid cross-contamination



Remediation Basics

- You can clean without disinfecting
- You can NOT disinfect without cleaning






189

Points to Remember

- Eliminating water is the best way to eliminate fungi
- You cannot disinfect and kill fungi without cleaning first
- Choose the right chemicals &/or equipment for the job and follow manufacturer's directions
- Healthy employees are the best







191

Work Site Hazards

Physical

- Confined Space
- Electrical
- Slips, Trips & Falls
- Heat-related disorders

Chemicals

- Asbestos containing materials
- Lead based paint
- Cleaners, disinfectants & sealers





Work Site Safety Hazards

- · Sharp objects
- Slippery surfaces
- · Falling objects
- Terrain
- Unstable surfaces
- Burns
- Improper lifting Ergonomic hazards

- · Pinch points
- Environmental (weather, animals, poisonous plants)
- Struck-by / Roll Over
- Public/Other Contractors
- Dehydration



193

Chemical Work Site Safety Hazards


- Asbestos Containing Materials (ACM)
- Lead (LBP)
- Chemicals
 - Cleaners
 - Disinfectants
 - Sealers





Work Place Hazards

OSHA's Hierarchy of Controls





195

Personal Protective Equipment

• 29 CFR 1910.132

"Protective equipment, including personal protective equipment for eyes, face, head, and extremities, protective clothing, respiratory devices...shall be provided, used and maintained whenever it is necessary by reason of hazards of processes or environment... capable of causing injury or impairment in the function of any part of the body through absorption, inhalation or physical contact." - OSHA



Protective Clothing

- · Protective Clothing
- Hoods and boots
- · Respirator inside of hood
- · Oversize suits for ease of movement
- · Reinforce suits with duct tape
- Tape wrists to gloves, ankles



197

Respiratory Protection

- Respirators are the last option after:
 - engineering controls
 - administrative controls
 - · work practices
 - · alternative materials
 - other methods



Personal Protective Equipment

Mold Remediation of Less than 100 Square Feet

Employees must wear the following:

- An N95 disposable respirator (i.e., a dust mask) in accordance with the OSHA respiratory protection standard (29 CFR 1910.134)
- Disposable protective clothing covering both head and shoes
- Gloves
- Eye protection



199

Personal Protective Equipment

- Note!

Employees using respirators must follow the requirements in SP 001:17:2, Respiratory Protection Safety Program.



Types of Respirators

• Three levels of particulate filter efficiency are 95%, 99%, and 99.97%. The three categories of resistance to filter efficiency degradation are labeled N, R, and P. The class of filter will be clearly marked on the filter, filter package, or respirator box.



201

Types of Respirators

- **Filter Efficiency** selection of filter efficiency (i.e., 95%, 99%, or 99.97%) depends on how much filter leakage can be accepted. Higher filter efficiency means lower filter leakage.
- Oil Resistance selection of N-, R-, and P-series filters depends on the presence or absence of oil particles, as follows: If no oil particles are present in the work environment, use a filter of any series (i.e., N-, R-, or P-series).
 - If oil particles (e.g., lubricants, cutting fluids, glycerine, etc.) are present, use an R- or P-series filter.


Note: N-series filters cannot be used if oil particles are present.

 If oil particles are present and the filter is to be used for more than one work shift, use only a P-series filter.

ENVIRONMENTAL EDUCATION ASSOCIATES

Types of Respirators

- Half Face Negative Pressure
- N100 Fitted Facepiece









203

Types of Respirators

• NIOSH Video

"A Particle is a Particle"



Respiratory Program

- Minimum Requirements:
 - -written SOP
 - MSHA/NIOSH certified respirators
 - appropriate for hazard
 - training of wearer
 - individual respirators

- cleaning & disinfection
- respirator storage
- inspection & repair
- -work area monitoring
- medical review
- annual evaluation of respiratory program



205

Other Important Issues

- · Medical fitness to wear a respirator
- Facial hair & respiratory protection
- Care & cleaning of respirators
- · Inspection of respirators
- · Cleaning & disinfection
- Repairs
- Storage



Asbestos: What Is It?

- Asbestos minerals share some common characteristics:
 - Naturally occurring from Ores rich in Magnesium, Calcium, Silica, and Iron
 - High tensile strength along the axis of the fiber
 - Chemically inert
 - Non-combustible



207

Definitions

ACM= Asbestos Containing Materials

 This is any material that contains greater than 1% asbestos fibers

PACM=<u>P</u>resumed <u>A</u>sbestos <u>C</u>ontaining <u>M</u>aterials

 This is any TSI, Surfacing, or Misc vinyl/asphalt flooring or roofing installed before 1980



Mold on ACM



ACM- Pipe insulation (T.S.I)



ACM- Spackle/Joint compound



209

ACM at NYCHA



ACM- Pipe insulation (T.S.I)




ACM - Flooring



Lead Based Paint

On mold remediation projects lead based paint can also be impacted.

- It will typically be in the paint on or near the areas with mold growth
- Demolition or removal of these painted surfaces can create potentially dangerous exposures to lead dust and lead contaminated debris





211

Why are Dust and Debris a Problem?

- Remediation activities that disturb lead-containing materials create dust and debris
- · Lead-contaminated dust is poisonous
- Very small amounts of lead-contaminated dust can poison children and adults
 - -Children swallow dust during ordinary play activities.
 - Adults swallow or breathe dust during work activities.
- Workers can bring lead-contaminated dust home and poison their families



Lead Renovations

- EPA requires that those conducting renovation, repair & painting obtain RRP certification and use Lead Safe Work Practices (LSWP)
- HUD requires LSWP for activities that disturb more than 2 sq. ft of painted surface in any one room



213

Hazard Communication

Mold remediation involves use of:

- Cleaners
- Disinfectants
- · Anti-microbials
- Biocides

Chemicals in these substances require that an employer have a hazard communication programs in place



Hazard Communication

The basic goal of a Hazard Communication Program is to be sure employers and employees know about work hazards and how to protect themselves; this should help to reduce the incidence of chemical source illness and injuries.



215

HAZCOM is RIGHT TO KNOW

OSHA has estimated that more than 32 million workers are exposed to 650,000 hazardous chemical products in more than 3 million American workplaces.*

Does this pose a serious problem for exposed workers and their employers ...

What do you think?



Case Studies

New York City Sanitation, November 1996



Michael Hanly, trash collector, killed while standing behind his truck as 70% hydrofluoric acid gas escaped from containers under compaction

City workers in another location find six plastic jugs of hydrofluoric acid placed curbside with recyclables





217

What Does This Standard Do?

 The HCS provides workers the right-to-know concerning the hazards and the identities of the chemicals they are, or may have the potential to be, exposed to in the workplace.



Steps to an Effective HAZ-COM program

- Hazard Assessment
- Develop a written HAZCOM Plan
- Appointment of a HAZCOM Coordinator
- Conduct the chemical inventory
- · Initiate labeling requirements
- Maintain the SDS library
- · Establish employee training



219

Hazard Determination

- The standard requires that employers inventory all hazardous chemicals in the workplace and include that inventory as a part of the written hazard communication program.
- This inventory will eventually serve as a master list for which a SDS must be obtained and maintained.



Establish Employee Training

 Each employee who may be "exposed" to hazardous chemicals when working must be provided information and trained prior to initial assignment to work with a hazardous chemical, and whenever the hazard changes.



221

Employee Responsibilities

- Know where to get information about hazardous substances used, stored, or handled at your inspection sites.
- · Learn to read labels and understand SDSs.
- · Identify hazards before you begin a task.
- Do not be afraid to ask questions.
- Use personal protective equipment.



Confined Spaces

NYCHA staff may encounter the following confined spaces during mold remediation:

- Roof fan housing
- Chimneys
- Interstitial spaces
- Elevator shafts
- Others?



223

Confined Spaces

- · Definition of a confined space is any space that
 - A person can enter
 - Has a limited opening for entry or exit
 - Is not designed for continuous occupancy
- A confined space that has any associated hazard is considered a permit-required confined space
- Hazards can include oxygen deficient or enriched atmospheres, toxic or flammable atmospheres, mechanical or electrical hazards, falls, engulfment, etc.



Confined Spaces

60% of confined space deaths are among would-be rescuers.

Don't become a statistic!



225

Electrical Hazards

- Electrocution and electric shocks are among the most common hazards.
- Incorrect wiring, improper grounding, and lack of proper insulation result in over 1,000 people being electrocuted each year



Worker Responsibilities

- Being aware of potential hazards
- Knowing how hazards should be treated
- Knowing what to do to protect themselves from electrical shock while working in a regulated abatement work area.





227

Hazard – Damaged Cords

- Cords can be damaged by:
 - Aging
 - Door or window edges
 - Staples or fastenings
 - Abrasion from adjacent materials
 - Activity in the area
 - Improper use can cause shocks, burns or fire







Hazard – Defective Cords & Wires

- Plastic or rubber covering is missing
- Damaged extension cords & tools









229

Hazard - Improper Grounding

- Tools plugged into improperly grounded circuits may become energized
- Broken wire or plug on extension cord
- Some of the most frequently violated OSHA standards







Clues that Electrical Hazards Exist

- Tripped circuit breakers or blown fuses
- Warm tools, wires, cords, connections, or junction boxes
- GFCI that shuts off a circuit
- Worn or frayed insulation around wire or connection





231

Slips, Trips and Falls

- Mold remediation sites present some significant risks for slips, trips and falls.
- Non-slip rubber boots or shoes with non skid soles can greatly reduce slips and falls when working on wet polyethylene
- No running, jumping, or "horseplay" should be allowed in the work area



Problems With Heat


- · The body naturally tries to cool itself by sweating
- If you are wearing an impermeable suit, your body heat cannot escape
- Your lungs are already in overdrive due to the added stress of the respirator
- The Air Conditioning has been shut off for the summer, and the air in the work area is much warmer than the air outside
- Perfect conditions for the onset of HEAT STRESS or HEAT STROKE



233

Hazard Recognition

Look at the BIG picture!





Hurt at Work

- · You've carefully thought out all the angles.
- · You've done it a thousand times.
- · It comes naturally to you.
- You know what you're doing, its what you've been trained to do your whole life.
- · Nothing could possibly go wrong, right?



235

Think Again!





NYCHA MOLD TRAINING



1

NYCHA MOLD TRAINING



Overview of Containment

- The goal of containment is to limit the spread of mold throughout the building in order to minimize the exposure of remediators and building occupants to mold.
- The larger the contaminated area, and the greater the possibility that someone will be exposed to mold, the greater the need for containment.





3

EPA Guidelines for Containment

Two types of containment are described in EPA's mold remediation guidance:

Limited- Limited containment is generally used for areas involving between 10 and 100 square feet of mold contamination.

Full containment- is used when areas larger than 100 square feet are to be remediated or in cases where it is likely that mold could be spread throughout the building during remediation



Limited Containment

- A single layer of 6-mil fire-retardant polyethylene sheeting enclosing the moldy area.
- Access to the contained area is through a slit entry covered by a flap on the outside of the containment area.
- Containment is generally recommended for areas involving 10 to 100 square feet of mold contamination.



5

Limited Containment

- In small areas, the polyethylene sheeting can be secured to the floor and ceiling with duct tape.
- In larger areas, a frame of aluminum extension poles or wooden studs can be built to hold the polyethylene sheeting.





Work Area Prep

- Pre-clean and install critical barriers
- Barriers are constructed to seal off all openings and penetrations to the work area
- Barriers to be constructed of 6 ml fireretardant poly sealed with duct tape



7

SP 040:18:2 , Lead Safety for RRP – Site Prep

In apartments, discuss the following with the resident:

- · Extent of containment needed
- · How the containment area will be prepared
- Advise residents <u>not to enter the containment area</u> <u>until after clean-up</u>
- Direct residents not to allow children to enter any area in which plastic sheeting is being used or stored due to the risk of suffocation



- Secure the apartment and/or work area against unauthorized entry.
- Move all objects out of the room, if possible.





9

Non-Movable Items



 Items which can't be moved must be cleaned, covered and sealed with two layers of 6 ml poly to protect them from damage and contamination



Signs

- Shall be displayed at all accessible entrances to remediation areas
- Should be in the language of the local population
- Should only be removed after final clean





11

SP 040:18:2 , Lead Safety for RRP – Site Prep

- Cover the floor of the work area with one layer of sixmil disposable polyethylene sheeting, and tape the sheeting down to prevent movement.
- The floor sheeting must extend six (6) feet in all directions from the work area where practical, unless vertical containment is installed. Use two layers of sheeting to cover wall-to-wall carpeting, overlapping the seams by at least six (6) inches.



 If vertical containment is used, the floor covering may stop at the vertical barrier, if it is impermeable, extends from the floor to the ceiling, and is tightly sealed at all floors, ceiling, and walls.





13





- Cover the work area entrance or vertical containment doorway with one layer of sheeting.
- Tape the sheeting to the top of the door frame or vertical containment high point and weigh down the bottom to create a seal.
- Create a door flap on the sheeting that allows access into the work area.





15

SP 040:18:2, Lead Safety for RRP – Site Prep

- Close and cover all forced air systems (HVAC) in the work area with one layer of disposable polyethylene sheeting, including bathroom vents, common area vents, exhaust vents, and hall vents.
- All supply and air vents, doors, and pipe chases in the containment area must be sealed with polyethylene sheeting to minimize the spread of mold and mold spores to other areas of the building.





- Close windows, and where applicable, cover the windows with one layer of sheeting to prevent dust and debris from settling on windowsills.
- Close windows, and where applicable, cover the windows with one layer of sheeting to prevent dust and debris from settling on windowsills.



17

SP 040:18:2, Lead Safety for RRP – Site Prep

- In kitchens and bathrooms, cover counter tops, cabinets, sink base cabinets, and all other horizontal surfaces with sheeting, to ensure that all doors and drawers are sealed.
- Cover the stove with sheeting and seal. Ensure that the stove is off and cool to the touch before covering.
- Cover and seal the refrigerator with sheeting. Prior to covering, cut slits in the sheeting to allow for ventilation.



Other items:

- Cover any items that cannot be relocated out of the work area.
- Tape the protective sheeting to the wall of the building or use a 2x4 wrapped in protective sheeting to hold the material next to the wall. Use heavy objects to weigh the other edges of the protective sheeting to the ground to secure.





19

SP 040:18:2 , Lead Safety for RRP – Site Prep

 When using ladders on plastic sheeting, place a sturdy piece of plywood on the plastic and then set the ladder on the plywood to prevent the ladder from puncturing the plastic and to provide a stable surface for the ladder. If plywood is used, take special care to secure it to the ground so that it does not move.



 Cover all items which were not moved from the work area with one layer of disposable polyethylene sheeting.

The sheeting must be taped together with duct tape, and taped to the floors or bottom of the walls or baseboards, to form a continuous barrier to the penetration of dust.



21

Work Area Prep Reminder!

- Work area must be cleaned (HEPA vac and/or wet methods)
 - Methods that raise dust are prohibited
- Pre-cleaning intended for preparation work only!
 - No disturbance of visible mold until containment is established




Work Area Prep

The time invested in prepping the work area is easily regained during the clean-up phase.

Mold Remediation - Containment Barrier



23



Wall Breaks

- When opening a wall to perform or prepare for repairs, staff must take the necessary precautions to protect residents and staff from mold, asbestos, and lead.
- This guidance (which supplements the wall break procedures detailed in SP 040:18:02) details the steps staff must take before, during, and after the wall break. Instructions on temporary wall closures are also included in this guidance; temporary wall closures are an important customer service practice that must be implemented until permanent repairs can be completed.
- Maintenance workers, bricklayers, carpenters, plumbers, plasterers and roofers are responsible for performing repairs that require wall breaks, and are responsible for following the below guidance.

ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities health

25

Asbestos Pipe Insulation



ACM Pipe insulation

- Asbestos containing thermal system insulation (TSI) may be present in wall cavities.
- Avoid disturbing and contact Tech Services if TSI is disturbed or must be disturbed

ENVIRONMENTAL EDUCATION ASSOCIATES Wirking to make our communities health

Work Area Prep

 Hands – On: Prepare an enclosure for containing mold contamination



27

Work Area Prep

After determining that a wall break must be performed, staff must immediately obtain the necessary supplies before proceeding with repairs.

Supplies include, but are not limited to:

- 6 mil polyethylene sheets
- duct tape
- a spray bottle
- a sheet of pre-cut Masonite



Work Area Prep

- Lay polyethylene sheets on all horizontal surfaces in the immediate vicinity of the wall opening and secure them with duct tape.
- Just prior to starting work, mist with water the surface area to be opened to reduce the amount of dust produced from the wall break.



29

Work Area Prep

- If you are working in a development with known lead-based paint or lead components (listed in Appendix A and B of SP 1040:18:02), polyethylene sheets should cover all horizontal surfaces in the room where the repairs occur.
- The entrance door should also be covered and weighted at the base to prevent dust from entering other rooms.
- In these developments, you should make every effort to keep the wall opening under two (2) square feet to limit the amount of dust produced.



Precautions while preforming repairs; Temporary Wall Closure

- Where possible, score painted walls with a utility knife or use a
 pry bar or chisel to open a glazed wall. Sawing and drilling
 should be avoided, if possible, as they produce significantly
 more dust and make containment and clean up more difficult.
- The wall opening should measure 1' by 1' when done for exploratory purposes (e.g., locating a leak), 2' by 2' for smaller repairs, and 4' by 4' for larger repairs.
- By opening the wall according to these standard sizes, staff can quickly and easily create a temporary closure using pre-cut Masonite. Developments should maintain a stock of Masonite cut in these sizes to fit the standard wall opening.



31

Precautions while preforming repairs; Temporary Wall Closure

 Staff must make a temporary closure over the opening so that residents are not left with an open wall until final repairs can be completed. Staff should place a pre-cut Masonite sheet over the opening and screw in to secure it. The edges should be covered with duct tape to seal it.



Precautions while preforming repairs; Temporary Wall Closure

- When the wall opening is performed on a <u>tub wall</u>, staff must waterproof the temporary Masonite closure. Use a new piece of polyethylene sheeting to cover the affected wall from the side and top edges to the tub ledge and extend 12 inches past the corner onto the adjacent wall, securing all edges with duct tape.
- Carefully cut an opening for the tub spout and shower controls, and tape down edges as thoroughly as possible.

ENVIRONMENTAL EDUCATION ASSOCIATES

33

Precautions while preforming repairs; Temporary Wall Closure – Note!

 Staff are required to detail that a wall opening has been performed on a tub wall in the notes section of the work order. The subsequent permanent repairs must be expedited in order to prevent potential damage to apartments below. To do so, staff must also notify the development supervisor(s), who will inform the Planning Unit that the follow-up work order must be prioritized.


ENVIRONMENTAL EDUCATION ASSOCIATES

Clean Up

- Once the temporary wall closure is complete, use a HEPA-filter vacuum to remove dust, then wet wipe the work area using a clean rag or moistened towel to remove any remaining dust.
- If you suspect lead is present, use a clean rag or moistened towel with lead-specific detergent to wipe down the work area.



35



Common Problems: Exhaust Grill



Dirty



Closed



Not sealed



37

Common Problems: Duct Shaft



Blocked






Dirty



Common Problems Imbalance

- Over-ventilation
 - Wastes energy
- Under-ventilation
 - Leads to poor IAQ and possible mold





39

Solutions: Ventilation

- Clean duct shafts/branches
- Clean or replace exhaust grilles






Instructions for Cleaning Horizontal Vent Ductwork

When cleaning horizontal vent ductwork from inside the apartment, employees:

- (1) Remove the face of the grill to the vertical shaft and HEPA-vacuum the grill and the interior and exterior of the horizontal vent ductwork.
- (2) Must use caution when cleaning the fire damper inside the ductwork.





41

Anemometers

- Used for measuring the speed of air flow
- Maintenance staff will measure air flow after vent cleaning





Anemometers

- NYCHA uses Testo
 Vane instrument
- Must be set to Cubic Feet per Minute (CFM)
 unit for Air Volume measurements.
- Must be calibrated to 15% free air





43

NYCHA MOLD TRAINING EEA ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities healthy

Background

- When performing repairs that require a wall break and/or repairs to water/ fire system piping or heat supply lines, NYCHA has the opportunity to quickly and efficiently retrofit piping with insulation in accordance with New York City code.1
- This Interim Guidance provides information on how to inspect and install insulation when a wall break has been performed in the course of completing a repair.
- Maintenance workers, bricklayers, carpenters, plumbers, plasterers and roofers are responsible for conducting repairs that require wall breaks and/or repairs to water piping. <u>Thus,</u> <u>maintenance workers and the aforementioned trades will be</u> <u>responsible for following the below guidance.</u>

ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities heal

45

Process Details

For repairs requiring a wall containing pipes to be opened, maintenance and applicable skilled trades staff are instructed to inspect pipes, valves and fittings exposed for the presence of insulation.

- apartment repairs staff must inspect all domestic water pipes for insulation
- public space staff must inspect water/ fire system piping or heat supply lines affected by the repair
- All new piping (other than waste, vent piping and heat return lines) must be insulated and any repairs that require removal of insulation must include replacing the removed insulation

ENVIRONMENTAL EDUCATION ASSOCIATES

Asbestos Pipe Insulation



ACM Pipe insulation

- Asbestos containing thermal system insulation (TSI) may be present in wall cavities.
- Inspector should inspect all risers, t's and fittings both in the area and distal from the wall opening



47

Toilet Supply Line



 Condensation on uninsulated toilet supply line can lead to moisture on walls and floors



Process Details

- If there is no insulation present, staff must install insulation on all pipes, valves and fittings exposed and accessible as a result of the wall break.
- Where possible, one-inch thick insulation should be installed. If pipe spacing prevents one-inch insulation to be installed, half-inch thick insulation should be installed.



49

Fiberglass Insulation

- Use the charts below to determine what size fiberglass pipe insulation to order.
- There are two charts each for different types of piping. The Copper Pipe chart is for copper piping only and the Iron Pipe chart is for most non-copper piping (Iron, Black, PVC, CPVC, Sch 40/80 etc).
- The charts list the pipe size, the outside diameter measurements of the pipe, the circumferences around the pipe, and the size to order.





Fiberglass Insulation

FIBERGLASS PIPE INSULATION E-Z SIZE CHART FOR IRON PIPES

IRON PIPE SIZE	OUTSIDE DIAMETER	PIPE CIRCUMFERENCE	ORDE THIS S	
1/2"	7/8"	2-5/8"	1/2	х
3/4"	1-1/8"	3-1/4"	3/4	X
1"	1-3/8"	4-1/8"	1	X
1-1/4"	1-5/8"	5-1/4"	1-1/4	X
1-1/2"	1-7/8"	6"	1-1/2	X
2"	2-3/8"	7-1/2"	2	x
2-1/2"	2-7/8"	9"	2-1/2	x
3"	3-3/8"	11"	3	х
4"	4-3/8"	14-1/8"	4	X
5"	5-3/8"	17-1/2"	5	X
6"	6-5/8"	20-3/4"	6	X
7"	7-5/8"	24"	7	X
8"	8-5/8"	27-1/8"	8	x
9"	9-5/8"	30-1/4"	9	x
10"	10-3/4"	33-3/4"	10	x
11"	11-3/4"	36-7/8"	11	X
12"	12-3/4"	40"	12	X

FIBERGLASS PIPE INSULATION E-Z SIZE CHART FOR COPPER PIPES

COPPER PIPE SIZE	OUTSIDE DIAMETER	PIPE CIRCUMFERENCE	ORDER THIS SIZE	
1/2"	5/8"	2"	5/8 x	
3/4"	7/8"	2-5/8"	1/2 x	
1"	1-1/8"	3-1/4"	3/4 x	
1-1/4"	1-3/8"	4-1/8"	1 x	
1-1/2"	1-5/8"	5-1/4"	1-1/4 x	
2"	2-1/8"	6-5/8"	2-1/8 x	
2-1/2"	2-5/8"	8-1/4"	2-5/8 x	
3"	3-1/8"	9-3/4"	3-1/8 x	
4"	4-1/8"	13"	4-1/8 x	
5"	5-1/8"	16-1/8"	5-1/8 x	
6"	6-1/8"	19-1/4"	6-1/8 x	



51

Process Details

- Owens Corning ASJ Max insulation of both sizes and related materials (or other manufactured insulation approved by Supply Chain Operations) will be available in the development storeroom for maintenance and skilled trades staff to install on water pipes of various sizes.
- The full list of insulation and related materials is included in Appendix A.
- Should they not be available in the development storeroom at the time of the appointment, staff should make a temporary closure to the wall opening using Masonite until the material is obtained at which point work may resume. (Please follow Interim Guidance for Wall Breaks)



Process Details

- Maintenance workers and applicable skilled trades staff are responsible for fully inspecting the pipes exposed and accessible after the wall is opened.
- Should they find these pipes lack insulation, they must install the insulation during the course of the repair. Staff should consult the manufacturer's installation instructions for additional information.
- Staff issued with a handheld device must take a photo of the installed insulation once they have completed the installation, select the appropriate insulation remedy codes and attach the photo to the work order in Maximo.



53

Process Details

- If staff finds that insulation is ripped, damaged or unsecured, staff should remove what remains of the old insulation, and then install insulation around all pipes, valves and fittings that are exposed and accessible as a result of the repair.
- In the event staff suspects existing insulation may contain asbestos, they are to report it to the development and follow the existing process for testing and abatement. Once insulation has been tested and/or abated, staff should resume installation as outlined above.

ENVIRONMENTAL EDUCATION ASSOCIATES

Process Details

- Superintendents, assistant superintendents, and skilled trades supervisors are responsible for ensuring that maintenance and skilled trades staff have properly inspected pipes and installed insulation and adhered to policy and procedure outlined in this interim guidance.
- Superintendents and supervisors should review the work orders where insulation has been installed and view the attached photos to evaluate the installation.
- Additionally, superintendents and development staff are responsible for ensuring that an adequate supply of insulation is in stock, monitoring the supply, and ordering additional insulation, when necessary.

ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities healthy

55

NYCHA MOLD TRAINING EEA ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities healthy Assurance Assurance

Cleanup Method

- Method 1: Wet vacuum (in the case of porous materials, some mold spores/fragments will remain in the material but will not grow if the material is completely dried). Steam cleaning may be an alternative for carpets and some upholstered furniture.
- Method 2: Damp-wipe surfaces with plain water or with water and detergent solution (except wood – use wood floor cleaner); scrub as needed.
- Method 3: High-efficiency particulate air (HEPA) vacuum after the material has been thoroughly dried. Dispose of the contents of the HEPA vacuum in well-sealed plastic bags.
- Method 4: Discard Remove water-damaged materials and seal in plastic bags while inside of containment, if present. Dispose of as normal waste. HEPA vacuum area after it is dried.

ENVIRONMENTAL EDUCATION ASSOCIATES Working to make our communities health

57

Cleaning Methods

- HEPA vacuum surfaces
- Damp-wipe & dry
- HEPA vacuum surfaces again
- Discard in plastic as C&D waste
- HEPA vacuum entire work area





Cleaners & Disinfectants

- Specialized chemicals for mold remediation
- · Anti-microbial cleaners used first
- Disinfectants used AFTER cleaning is complete
- NYCHA Products



Fungicides/ Fungistats

- Sodium Tetraborate
- Quaternary Ammonium Compounds
- · Other Disinfectants
- NYCHA Products



61

Sodium Tetraborate:



- Advantages
 - Cheap
 - Effective
 - All natural
 - Readily available



Quaternary Ammonium Compounds



- · Advantages
 - Excellent Cleaner
 - Effective in organic soil
 - Mildewstatic properties
 - Safe
- Disadvantages
 - Need to keep using until the mold's food source or water is eliminated



63

Fosters 40-80



- Use as a disinfectant, sanitizer, cleaner, fungicide, deodorizer, virucide and germicide.
- Kills a large variety of microbes within minutes.
- Contains surfactants to help clean and remove residue.
- Designed for use in water damage restoration situations.



NYCHA Products

 Micro Bio- Wash Cleaner





65

Follow Manufacturer's Directions

- Use the right dilution
- Use the right application
- · Change solution when recommended
- Avoid cross-contamination


















Cleaning Methods

- You can clean without disinfecting
- You can NOT disinfect without cleaning





Mold Resistant Paint



- Applied after surfaces are cleaned, disinfected & dry
 - Apply per manufacturers instructions



75

Anti-microbial coatings

- Used to treat building materials prone to mold growth
- Applied to framing and drywall, among other substrates during new construction or after remediation
- Long term protection against mold and mildew growth.



NYCHA Products

Fosters 40-50
 Anti-Microbial
 Coating





77

New Developments

Plast-tec waterproof barrier

- Ready to use for an interior or exterior floor
- · Mold and mildew resistant





New **Developments**

 Mold-resistant caulking securely bonds to a variety of substrates and finishes, including glass, ceramic, porcelain, tiles, stainless steel.

including glass, ceramic, porcelain, tiles, stainless steel, plastics, glazed surfaces, imitation marble, aluminum, and many composite materials.





79

Disposal

- Removal of Containment Materials
 - 6 mil Contractor bags
 - Goose-neck sealed
 - Decontaminated
 - Taken directly to secure container





Goose-necking

· How to goose-neck a waste bag



81

Quality Assurance Inspections

- Maximo automatically generates a quality assurance inspection work order twenty-five (25) days after the last child work order is closed for all apartments where a mold, water damage, or moisture (i.e. a wet measurement) condition was identified during the inspection. The target start date is automatically populated as 30 days after the last child work order closed and the target end date is populated as 45 days after the last child work order closed.
- Once the quality assurance inspection work order is generated, property management staff contacts the resident and schedules the quality assurance inspection to take place between 30-45 days after the last child work order is closed. See Section VIII.A.3 for the process to schedule appointments.



Quality Assurance Inspections

Inspecting for Mold, Water Damage, and Moisture

The Inspector:

- Visually inspects for mold any wall, floor, ceiling, or component identified in the initial inspection as having mold and records the results in the handheld device.
- Visually inspects for water damage any wall, floor, ceiling, or component identified in the initial inspection as having water damage and records the results in the handheld device.
- Uses the moisture meter to measure for subsurface moisture any, wall, floor, ceiling, or component that measured wet during the initial inspection and records the results in the handheld device.



83

Quality Assurance Inspections

If all work was satisfactorily completed:

 The inspector completes the quality assurance inspection by taking photo(s) of the inspection area free of mold, water damage, and/or moisture and uploading the photo(s) into Maximo.

If any work was not satisfactorily completed:

The inspector:

- · Immediately creates a child work order in Maximo.
- Takes and uploads a photograph of the unsatisfactory work into Maximo if the work is visible in the apartment.
- · Closes the existing quality assurance inspection work order.
- Follows up with supervisor of the staff person(s) who performed the work to report the unsatisfactory work and ensure the work is completed.



Quality Assurance Inspections

If any work was not satisfactorily completed:

The inspector:

- · Immediately creates a child work order in Maximo.
- Takes and uploads a photograph of the unsatisfactory work into Maximo if the work is visible in the apartment.
- Closes the existing quality assurance inspection work order.
- Follows up with supervisor of the staff person(s) who
 performed the work to report the unsatisfactory work and
 ensure the work is completed.




85

Simulation & Practical Scenario

- Virtual Reality
- COVID Rules
 - Don't participate if you think you might not feel well
 - Use a clean headset
 - Segregate after use so that the headsets can be decontaminated
 - Wash you hands after use.



NYCHA MOLD TRAINING



87

Outputs

- Mold in NYCHA apartments is remediated and the root causes are identified and corrected within the allowable timeframes.
- · Mold recurrence is reduced



Performance Reporting

NYCHA shall centrally assign...

Staff to review reports to identify developments with:

- · High parent mold work order completion time frames.
- · High rates of unfounded mold work orders.
- · High reoccurrence rates for mold work orders.



89

Performance Reporting

NYCHA shall centrally assign...

Supervisory staff trained in mold inspections to:

- Visit developments and inspect randomly selected apartments with high rates of unfounded or reoccurring (as applicable) mold work orders.
- Report findings on the underlying issue, i.e. a building system and/or mold inspection and remediation process issue.
- Provide follow up recommendations to the regional asset manager.



Performance Reporting

- For building system issues, the supervisory staff may, for example, recommend additional repairs.
- For process issues, the regional asset manager follows up with the property manager and property maintenance supervisor to address the process issue which could include providing additional training, reviewing key accountabilities, or providing progressive discipline.



91

Reports

 Operations reports to be developed with the independent data analyst



Record Keeping

 The IT Business Solutions Technology Department's Maximo Team retains electronically created and stored completed work orders for at least seven (7) years



93

 The IT Business Solutions Technology Department's Maximo Team retains electronically created and stored completed work orders for at least seven (7) years



Course Review



- Mold growth is always associated with excessive moisture problems.
- How do we prevent or control excessive moisture and what are the Root-Causes of excessive moisture?



95

Knowledge Assessment

• 20 question quiz

